

**11090**

SUPPORTS & STOPS


### Tips

Eliminates workpiece chatter and vibration during machining.

Easy to actuate; locate and fix beneath workpiece, turn actuation handle and sprung loaded support will come into

contact with workpiece. Lock handle to set support.

Order No.	Support height	$w_1$	$d_1$	$l_1$	$l_2$
11090.W0060	28	45	6	56	20



place the support under the workpiece and turn actuation until contact is made, continue to turn to set support height