



Chain Clamp Sets - 16kN

for large diameter clamping







12750

Material

Clamp: as part no. 10650. Chain: steel, 19,05mm pitch - 1 metre. Chain anchor: steel. Quick chain link: steel.

Technical Notes

Provides strong and even clamping of large

diameter workpieces.

Extra lengths of chain can be ordered and linked together.

Clamp or unclamp with a simple turn of the red key. The chain can then easily be removed clear from the workpiece.

Tips

Chains with rubber protective pads can also be provided on request (min. radius 200mm).


Order No.		D	escription			h_1	h ₂		h ₃	I_1	l ₂
12750.W0040	Set: Clamp, 1m Chain, Chain Anchor					89	49		-	108	12.5
12750.W0900	Chain - 1m					-	-		-	-	=
12750.W0905	Quick Chain Link					-	-		-	-	-
12750.W0910	Chain Anchor					-	-		22	-	-
Order No.	l ₃	I ₄	I ₅	\mathbf{w}_1	w_2	w ₃	W_4	A/F	Clamp	reach s ₁	Clamping force kN max.
12750.W0040	-	-	-	40	16	-	-	11	3	33	16
12750.W0900	-	-	19.05	-	-	19.5	-	-		-	-
			1005								
12750.W0905	-	-	19.05	-	-	-	-	-		-	-





Chain Clamp Sets - 16kN for large diameter clamping







Chain Clamping Set

Our comprehensive range of clamping elements includes a compact and powerful workpiece clamping element, the chain clamping set no. 12700. This set was specifically designed for clamping large workpieces with round or arched surfaces. Due to an increase in the bearing surface of the chain, the clamping force is distributed across the workpiece thereby reducing deformation.

Setting Up



 Attach the hook unit and the take-up unit as close to the workpiece as possible.




 Turn the knurled nut on the take-up unit until the pull rod is fully extended. Select the number of chain segments required for the workpiece and attach to the pull rod.



3. Fine adjustment of the chain lengths is made by tightening the knurled nut until the chain slightly touches the workpiece.



4. To clamp the work piece connect the free end of the chain onto the hook unit. Using a hex key tighten the eccentric shaft, and ensure the lever is rotated to its fully locked position (180°). The workpiece is now clamped.



Important Factors in Selection of Chain Clamp

The clamping force achievable through the Wixroyd chain clamp set is dependent upon three factors:

- Workpiece diameter (see graph).
- Chain length and stretch (see graph).
- Contact angle of chain and workpiece (see table below right).

	n Length (m)								
6,5										
6,0					+					
5,5	5,4						Chain s	troke g	(M16) = 30 r	nm
5,0	0,4									
1,5					\perp				27,	5
1,0										
3	3,6	Cł	nain stroke	g (M12) = 10	6 mm		2	22,0		
3,5						19	6			
3,0						16,5				_
2,5					4					
2,0			9,0	110						
,5			//	11,0						
,0	4,	5					M12 ch	ain upto	45 Nm	
	//	5,5				→	M16 ch	ain upto	90 Nm	
),5										
0 💆		5,0	10	0,0	15,0	21	0,0	25	0	3

Chain Length and Stretch

Torque value of 50 Nm is used for M12 set.

Torque value of 90 Nm is used for M16 set.

	a de la constantina della cons	el el el	O.C.	
	-8,/		1.6	
			10-0	
-	1000			
10				

Clamping with the chain clamp set.

	Torque	α = 105°	α = 120°	α = 135°	α = 150°	α = 180°
M12	50Nm	80%	87%	92%	97%	100%
M16	90Nm	80%	87%	92%	97%	100%

Important Note: Achievable clamping force decreases as the contact angle of chain and workpiece (α) reduces. Please use the table above as a guide.

Table of Clamping Force to Contact Angle α

